

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 51N N.R. 36W


Houghton COUNTY

DESCRIPTION OF CORNER Section corner for sections  $\frac{14}{23}$  |  $\frac{13}{24}$

CORNER MONUMENT 3/8" X 24" reinforcing rod 6" below road surface.

DATE MONUMENT PLACED AND WITNESSED 9-19-62

WITNESSES TO CORNER..... 9" Elm (NBT) N02°E, 59 links



12" Hard Maple (NBT) S02°E, 62 links

U. S. Geodetic Survey bench Mark, N62°W, 95 links

AND

CIRCLE CORNER REGISTERED

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed in  $\frac{1}{2}$  of gravel road and proportioned distance to corners 1 mile to east and west, distance to corner south checks good. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 26, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler