

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51N R. 36W


Houghton COUNTY

DESCRIPTION OF CORNER Section corner/^{common}to sections 28-29-32-33

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9-12-62 with L. Stevens, D. F.

WITNESSES TO CORNER..... 6" Cedar (S33 NBT) S72°E, 43 links



14" Hemlock (S28 NBT) N8°E, 76½ links

7" Tamarack (S32 NBT) S89°W, 83 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old wood post and 3/4" iron pipe set by unknown surveyor. Found no evidence of original corner. Position checks with original corner one-half mile to north.

Corner lies 1 chain north of old R.R. grade.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 26, 1963
REGISTERED LAND SURVEYOR

Billy D. Buckler