MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_51_ NR_36 W__

			-	Houghton	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner bet	ween Sec.'s 16-17	
DESCRIPTION	OF	CORNER	MONUMENT_1"	pipe with 4" brass	cap
WITTNESSES	то	CORNER	10" Y. Birch	N 82° E	35 links
			12" Hemlock	"1/4 S NBT" N 35° W 1/4 S NBT"	82 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one sugar B.T. bearing west 21 links. Tree green but in poor condition.

Position checks with 50" white pine stump 4.77 chs. to south. This is a probable line tree.

Chainage checks with good section corner 1/2 mile north.

Corner found by Forestry Division Survey Crew.

Corner placed and witnessed December 3, 1957.

SURVEYORS SEAL