

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 21 .. NR. 36 W. ..

..... Houghton COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec. 's 11-14

DESCRIPTION OF CORNER MONUMENT 1" pipe with 1/4" brass cap

WITNESSES TO CORNER 14" Hard Maple .. N 77° E .. 46 Links ..

"1/4 S NBT"

14" Hard Maple .. S 17° E .. 91 Links ..

"1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one probable sugar B.T. bearing N 28° E 24 links.
Tree green but rotted out inside.

Found several old blases in vicinity. Position checks with corners, streams
and swamp edges in area.

Found by Forestry Division Survey crew.

Corner placed and witnessed December 31, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buehler
REGISTERED LAND SURVEYOR

DATE 1/23/58