

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51. NR. 36. W

Houghton COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Section 8 and 9

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 12" Hard Maple (1/4s NBT) S 2° E 42 Links

12" Hard Maple (1/4s NBT) N 76° W 42 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was re-established midway and on line between two Section corners. No evidence of original corner. Found old blazes north and south of corner.

Corner was placed and witnessed September 1, 1959.

SURVEYORS SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/25/60