

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..51.. NR..36..W

..H o u g h t o n .. COUNTY

DESCRIPTION OF CORNER ..Section corner common to Section 14, 15, 22, and 23

DESCRIPTION OF CORNER MONUMENT ..1" Pipe with 4" Brass Cap ..

WITNESSES TO CORNER ..8" Hard Maple .. (S 15 NBT) .. N 38° W .. 16 Links ..

7" Yellow Birch (S 22 NBT) .. S 20° W .. 42 Links ..

6" Yellow Birch (S 23 NBT) .. S 37° E .. 31 Links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was replaced at wood post. No evidence of original corner.
Found old blazed lines to west, north and south.

Corner was placed and witnessed October 8, 1959.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/25/60
REGISTERED LAND SURVEYOR
Billy D. Buckler