MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_51 NR_36 W

_H Q M g_n_t_o_n COUNT
DESCRIPTION OF CORNER Section corner common to Section 3, 4, 9, and 10
DESCRIPTION OF CORNER MONUMENT_Public Fishing Site Monument.
WITNESSES TO CORNER 12" Hard Maple (NBT) N 42° E 25 Links
10" Hard Maple (NBT) N 56° W 27 1/2 Links
9" Hard Maple (NBT) 5 46° E 28 Links

RESTORED. This corner was re-witnessed as det by Fish Division. Found Pine stumps (possible line trees) north, south and west of corner. Distances west and south to lake check. Numerous blazes at corner.

Corner was placed and witnessed October 13, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Silly D. Suchler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/26/60 _