

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 51 .. NR. 36 .. W

.. H o u g h t o n .. COUNTY

DESCRIPTION OF CORNER Section corner common to Section 4, 5, 8, and 9 ..

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap ..

WITNESSES TO CORNER 10" Hard Maple .. (S 4 NBT) .. N 87° E .. 51 1/2 Links

14" Hemlock (S 8 NBT) .. S 44° W .. 25 Links ..

15" Soft Maple (S 5 NBT) .. N 66° W .. 18 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced as set by unknown surveyor. Found very old blazes at
corner. Position fits with bayou to west. Distance north and south to good
corners check ok.

Corner was placed and witnessed October 13, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler .. DATE 2/26/60 ..
REGISTERED LAND SURVEYOR
Billy D. Buckler