## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

		Houghton	COUNTY
		T	R 34-35W
DESCRIPTION OF CORNER	Section Corner 7, 12, 13,	and 18	
CORNER MONUMENT 1" I.	D. x 18" iron pipe with 4" a	luminum cap	<del></del>
DATE MONUMENT PLACED AN	D WITNESSED May 23, 197	2	
WITNESSES TO CORNER	Nail in power pole S330	W (mag.) 56.5 ft.	
N   13   13	W. Pine 10 N23°E (mag.)	<del>=¥23<sup>0</sup>E (==g)</del> 87.	6 ft. "S7, NBT"
	AND		
CIRCLE CORNER REGIST	ERED		
DESCRIPTION IN DETAIL A	S TO HOW CORNER WAS LOCATED	AND IDENTIFIED OR	RESTORED.
			_

Corner re-established at approximate intersection of centerlines of an E & W county road and a N & S county road, and approximately in line with an old fence and field edge to north, which is assumed to be the described corner by common report. Measurements southward along the township line tend to support the location.

SURVEYOR'S SEAL

	SIGN
DISTRIBUTION:	

REGISTERED LAND SURVEYOR DATE September 15, 1972

Forestry Division, Lansing

Area	Fore	ester		
Dist	rict	Surveyor		