MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_52 NR \$5 V.

			Meughton COUNTY
DESCRIPTION	OF	CORNER	Section Corner common to Sections 25,26,35,36
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with A" Bress sep
WITTNESSES	то	CORNER	14" Cedar - E 55 E - A5 Links
			10° Fewlock - S 40 T - % Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey ores, while making a partial resurvey of this Tourship. Corner had been previously located by unknewn Surveyor. One original B.T. still in place, down, in fuir condition.

Ocrner was placed and witnessed September 23, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 1/25/5/