

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 52 N. R. 36W


Houghton COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 32-33

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/10/63

WITNESSES TO CORNER..... 8" Cedar (1/2 S MBT) S45°W, 29 Lks.



10" Cedar (1/2 S MBT) N38°W, 27 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from (2) two Wood stakes bottoms. Y. Birch 10", N80°E, 24 Links, in proper position but badly rotted. Old blazes in vicinity.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 8/17/1964
REGISTERED LAND SURVEYOR