## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 52 N.R. 36 W

			Houghton		_ COUNTY
DESCRIPTION OF CORNER	Section Corner i	for Sections 15,	16, 21, 22		
CORNER MONUMENT 11	Iron pipe with 4	Aluminum Cap			
DATE MONUMENT PLACED A	ND WITNESSED	0-16-63	<u> </u>		<u> </u>
WITHESSES TO CORNER	7" Hemlock	(S 15) (NBT)	N 21° E	38 links	
N2	14" Hemlock	(S 22) (NBT)	S 28° E	32 links	
CIRCLE CORNER REGIATER	AND				

## DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from wood post found by Copper Ranger Co. who found Hemlock  $B_{\bullet}T_{\bullet}$ 

No original evidence now. Corner checks good with stream to South and West.

SURVEYOR'S SEAL

SIGNED SILLY SUCKER

Billy D. Buckler

\_\_\_\_

DATE <u>April 13. 1964</u>