

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 52 N.R. 36 W


Houghton COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 10, 11, 14, 15

CORNER MONUMENT 1 1/2" Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 10-16-63

WITNESSES TO CORNER..... 9" Hemlock (S14)(NBT) S 40° E 26 links



12" (Twin) Hemlock (S15)(NBT) S 77° W 48 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was set by unknown party.

Several blazed trees in vicinity. Also possible Sugar 6" B.T. N 70° W 08 links standing.

Other B.T. Sugar 6" S 40° E 14 links (down and rotted).

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 13, 1964
REGISTERED LAND SURVEYOR
Billy D. Buckler