## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. <u>51 &52</u> N.R. <u>36W</u>

		M
DESCRIPTION OF CORNER	Section Corner common to Secs. 5-6 9511 1364 & 31-32 9521 136	<u></u>
CORRER MONUMENT 14	Iron Pipe	_
DATE MONUMENT PLACED A	ND WITHESSED 10/10/63	_
WITHESSES TO CORNER	11" Hard Maple (S6 MBT) S12°W 34 Rts.	_
N	9" Black Cherry (S5 IBC) S42°E 50 Lts.	_
<b>+</b>	21" Hard Maple (with Aluminum Tag) 149°W 18 1ks.	_
	AND	
CIRCLE CORNER REGISTERS		_

## DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-witnessed a  $1^n$  Iron Pipe as set by Copper Range Company. No Original Evidence.

SURVEYOR'S SEAL

Silly V. Suchler

DATE <u>7/30/1964</u>