

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>53</u> N. <del>S.</del> R. <u>32</u> <del>E.</del> W.	<u>D3</u>
2. PROPERTY CONTROLLING IN SECTION <u>5</u>	T. <u>53</u> N. <del>S.</del> R. <u>32</u> <del>E.</del> W.	<u>16</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____ W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 24, 19 78, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on July 24, 19 78, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

**Corner D3: Original Monument and Accessories Not Found. Found 1" O.D. iron pipe in concrete set by William W. Stockly.**

**Corner 16: Found 1 1/4" I.D. iron pipe in concrete.**

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**Corner D3: Re-established at 1 1/4" O.D. Iron Pipe.**

**Corner 16: Established at 1 1/4" I.D. Iron Pipe in concrete.**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**Corner D3: 1" O.D. Iron Pipe in concrete in ditch on north side of County Road.**  
 DNR reference tag and nail:  
 7" Spruce N36E 13.90 ft.  
 9" Aspen N69W 21.00 ft.  
 7" Maple S22E 62.33 ft.

**Corner 16: 1 1/4" I.D. Iron Pipe in concrete in ditch on north side County Road.**  
 DNR reference tag and nail in: 9" R. Pine N15E 14.05 ft.  
 5" R. Pine N20 W 14.38 ft.  
 9" Spruce S13W 44.32 ft.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_


SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Keith L. Sackett DATE August 30, 1978

CHIEF OF SURVEY PARTY  
Keith L. Sackett  
 MICHIGAN REGISTERED LAND SURVEYOR  
 Michigan Department of Natural Resources



SURVEYOR'S MICHIGAN REGISTRATION NO. 19006