LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 53 N. R. 32 W.	E3, E2	-
2. PROPERTY CONTROLL- ING IN SECTION—	,T. 53 N. R. 32 W.	8	_
3. MISCELLANEOUS PROPERTY IN SECTION	,T		_
4. LOT NO, REC	CORDED PLAT	<u> </u>	_
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in lines 1 and 2 above were, in a field survey on July 20, 198, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on July 20, 1978, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration: Corner E3: Original Monument and Accessories Not Found. Found 1" O.D. Pipe in concrete buried in County Road. This monument set by William W. Stockly. Corner E2: Original Monument and Accessories Not Found. Found 1" O.D. pipe in concrete buried in county road. This monument set by William W. Stockly. Corner 8: Found 1" O.D. pipe in concrete buried in old road. This corner set by William W. Stockly on section subdivision. B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Corner E2: Re-established at monument. Corner 8: Re-established at monument.			
Nail and DNR referen Nail and DNR referen Underground cable ma Corner E2: 1" O.D. i Nail & DNR reference Nail & DNR reference	ron pipe in concrete. ce tag in power pole : ce tag in power pole :	N54E 41.25 ft. 812W 136.20 ft. 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 7 8 8 8 8	the position of the corner: Corner 8: 1" O.D. iron pipe in Concrete raised with 1" I.D. x 24" iron pipe with 4" aluminum cap. Nail and DNR reference cag in: 7" Sugar S26W 26.18 ft. 3" Yellow Birch S57E 31.40 ft. 3" Maple NO9W 35.90 ft.
SICNED BY		DATE	
SURVEYOR'S MICHIGAN REFOR STATE AND UNITED S			
SIGNED BY		DATE	August 36111978
APPROVED AND SIGNED BY	CHIEF/OF BURYEY PARTY	2: 1 DATE	August 30 11978
WITHOUTH WIND STORED BI	Michigan Registered Lai Keith L. Sackett Department of Natur	AD BURVEYOR	LANGRACATION
SURVEYOR'S MICHIGAN RE	GISTRATION NO. 19006		1900
	FORM API	PROVED BY MICHIGAN STATE E	BOARD OF RÉMMETRATION, JAN: 28, 1971 REVISED MAY 14, 1975

NAME OF ALMS ASSESSED AND BACK OND APPACHIED SHIEFT