## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. \_\_\_\_53 \_\_\_ N.R. \_\_34-35 W\_

		Houghton	COUNTY
DESCRIPTION OF CORNER 1/4 Corner betw	reen Sections 12 a	nd 7	
CORNER MONUMENT	Brass Cap		
DATE MONUMENT PLACED AND WITNESSED	5/17/61		
WITHESSES TO CORNER10" Y. Birch	(1/4s NBT)	N 13° E	55½ Links
N	(1/4s NBT)	S 13°E	34 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood post and 3/4" Iron Rod set by unknown party. Birch, S 22° W 16" chopped out. No original marks, still standing, may be B.T. Hole in ground N 27° E, 21 Links where 16" sugar should be. Distance to corner south checks good.

SURVEYOR'S SEAL

SIGNED Silver DATE July 26, 1961

REGISTERED LAND SURVEYOR

Billy D. Buckler