## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 53 NR 34-354

			-	Но	ighton	COUNTY
DESCRIPTION	OF	CORNER	Section corner	common to	7-18-12-13	
DESCRIPTION	OF	CORNER	MONUMENT_1"	pipe with	4" brass cap	
WITTNESSES	то	CORNER	10" Hard Maple		34° E 7' NBT'''	43 links
			16" Hard Maple	S	9° E	25 links
			18" Hard Maple	N	18 NBT" 54 V 12 NBT"	$42\frac{1}{2}$ links
				<b></b>		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner, found 1" iron pipe in place. Found yellow birch B.T. bearing N 50° E 11 links in poor condition.

Found unrecorded witness tree, yellow birch 18" S 39° W 60 links. This tree scribed only with "S13".

Found by Forestry Division Survey Crew.

SURVEYORS SEAL