

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 34 W


Houghton COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 19-20

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/11/1966

WITNESSES TO CORNER..... 13" Cedar (1/4S NBT), S 16° E, 16.7 Feet



22" W. Pine (1/4S NBT), N 77° W, 7.4 Feet

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Corner from one Cedar Bearing tree, S 30° W, 21 Links; tree uprooted;
both scars visible with some overgrowth but no scribe marks.

Corner lies 50 Links North of a stream. N mention is made of this stream in
the Original Survey.

Distance South checks well to a Line Tree and the Section Corner.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 8/11/1966
REGISTERED LAND SURVEYOR