LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	T. 53 N. R. 35 W.	_ L7, L9	
2 PROPERTY CONTROLLS	,T N. R E.		
5. MISCELLANEOUS PROPERTY IN SECTION.	N. R. E. S., R. W.		
4. LOT NO	RDED PLAT		
S. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I. Keith L. Sackett			
B Description of corner evidence found and/or method applied in restoring or re-establishing corner: Corner L7: Found wood post set by unknown persons midway between two section corners. Corner L9: This corner re-established on line between section corner.			
Corner L7 and L9 re-established 6/16/66 by Regional Land Surveyor Billy D. Buckler but not recorded. Corner L7: Set 1" I.D. pipe with 4" aluminum cap. 13" Red Oak S57 E 23.5 Ft. 45 13/24 NBT 8" Sugar N61 W 19.0 Ft. 45 13/24 NBT			
Corner L9: Set 1" I	S.D. pipe with 4" alum S37 W 19.2 ft. 3	ninum cap. 45 NBT 45 NBT	
7" Y. Birch	1135 W 2400 W 40	•	
SIGNED BY			(SEAL)
SURVEYOR'S MICHIGAN RE		<u> </u>	
FOR STATE AND UNITED S	STATES AGENCIES:		THE OF MICHAEL
SIGNED BY	CHIEF OF SURVEY PAPTY	DATE.	7/27/36 KEIGH L.
APPROVED AND SIGNED B	MICHIGAN NEGIBIRAED E	AND BURVEYOR	LACYD WILVEYOR
	Keith L. Sackett		1900s
SURVEYOR'S MICHIGAN RI	EGISTRATION NO. 1	9006	DARD OF REGISTRATION, JAN. 28, 1971
	FORM A	TELEGRAPH BI MISHINGS SICH S	REVISED MAY 14 1975