

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53N N.R. 35W


Houghton COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ Corner for Sections 22/23

CORNER MONUMENT Wood post

DATE MONUMENT PLACED AND WITNESSED 8-24-61

WITNESSES TO CORNER..... 18" Hemlock ($\frac{1}{4}$ S NBT) S 24°E 26 $\frac{1}{2}$ links



12" Hemlock ($\frac{1}{4}$ S NBT) N89°E 26 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 14" Hemlock N65°W 7 links. B.T. down and rotted - Found portions of inverted scribe marks. 11" Maple N80°E 14 links in place but badly decayed.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE March 14, 1962
REGISTERED LAND SURVEYOR
Billy D. Buckler