

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 53 N.R. 35N


Houghton COUNTY

DESCRIPTION OF CORNER  $\frac{1}{4}$  Corner for sections 26

CORNER MONUMENT 1" Iron pipe with 4" brass cap.

DATE MONUMENT PLACED AND WITNESSED 8-22-61

WITNESSES TO CORNER..... 12" Hemlock ( $\frac{1}{4}$ S NBT) S 26°W 36 links



11" Hemlock ( $\frac{1}{4}$ S NBT) N 27°E 43 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from possible B.T. Hemlock 14" S 70°W 12 links. Marks made with scribe or sharp tool. Many blazed trees near. Streams & possible Hemlock line tree to east - check well.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 14, 1962  
REGISTERED LAND SURVEYOR  
Billy D. Buckler