CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 35W

		Houghton	COUNTY
DESCRIPTION OF CORNER	Section corner for Se	ctions 26 25	
CORNER MONUMENT	l" iron pipe with 4"	35 36 brass cap.	
DATE MONUMENT PLACED AND	WITNESSED 8-22-61		
WITHESSES TO CORNER	12" Cedar (S25 NBT)	N 62 ⁰ E 16 links	
	12" Elm (S25 NBT)	N 59°W 32 links	
CIRCLE CORNER REGISTERED	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from cedar 20" N 45°E 10 links, (with scribe marks plainly visible) and 20" Cedar S75°W 28 links, proper distance and bearing but no marks, badly weathered.

SURVEYOR'S SEAL

SIGNED Silly E. Suckles DATE March 14, 1962

REGISTERED LAND SURVEYOR

Billy D. Buckler