

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 35 W


Houghton COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 23-24-25-26

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/28/65

WITNESSES TO CORNER..... 8" H. Maple (S24 NBT), N 22° E, 22 Lks.



13" H. Maple (S25 NBT), S 39° E, 38 Lks.

5" Soft Maple (S26 NBT), S 46° W, 52 1/2 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner replaced at location of 3 Iron Pipes found by Frank Bray, 1957.

Corner lies on top of the East bank of a ravine.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 6/3/1966
REGISTERED LAND SURVEYOR