## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 53 N.R. 35 W

		H <sub>C</sub>	ought <b>on</b>	COUNTY
DESCRIPTION OF CORNER 3	/4 Corner between S	ecs. 25-26		
CORNER MONUMENT 18 I	ron Pipe			<del> </del>
DATE MONUMENT PLACED AN	D WITNESSED <u>11/4/65</u>			<u></u>
WITNESSES TO CORNER	13 Hard Maple (	1/4S NBT), S 05	W. 35 Iks.	
N	12* Hard Maple (	1/48 NBT), N 72	98 Iks	
25	8" Soft Maple (	1/4 <b>S</b> NBT), N 71	L E 65 Iks	
CIRCLE CORNER REGISTERES	AND			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed this Corner as placed by unknown Surveyor. Found no evidence of Original witnesses.

Iron Pipe appears to have been set midway and the mile and the East of a straight line.

SURVEYOR'S SEAL

Billy Q. Buckles.

SIGNED Billy IX Buckler

DATE 6/3/1966