MAY 17 2000

267 LAND CORNER RECORDATION CERTIFICATE

SECTION

For corners in	Filing Requirement	nt of Act 74, Mich. P.	A. 1970			
Houghton	Located in:	Corner Code #				
(County)		 - - - - - -	REGISTER'	S OFFICE	} ••	
	•		Houghton Co	ounty, Mich.	}	2000
 Public Land Survey 	T <u>55NR 33W</u>	L-9			the	95 1/1
	T <u>55NR 33W</u>	-(K-9)	of gulli	for record	D., 19.	(, 5)., Birijeer
	T <u>55N</u> R <u>33W</u>	K-10		M. and re		
2. Property Controlling	T R S T R		01.0.8.8.93	escent. T	2000	les
in Section	S T R	., ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•••••			Regis
3. Miscellaneous	S T R					
Property in Section	S T R		Register	of Deeds Sta	mp & Fi	le Number

	ecorded Plat			BCDE	F G	ніјк
5. Private Claims		, , , , , , , , , , , , , , , , , , , ,				
			ءً [
Ronald S.			3			
	in a field survey onAugust	11 19 07			,	0111
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned						
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land						
	a Court of Law and/or that the corner p			19 20	212	2 -23 - 2
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a						
Decree of a Court of Law; estate as expressed below:	olished, re-established, monumented, re	e-monumented, recovered,	found	-3029	-282	7-26-2
•	ners, all in the same town and rang		11	Ĭ-	الللة المستحدد	
on this certificate.	ners, ali in the same town and rang	e, may be recorded	12	31 32	-333	4 35 3
Y			13		لْـلــــــّــ	
A. Description of original r	monument and accessories and/or	r subsequent restoration	n:(From o	rig. note	es da	ted 1846
L-9 (S1/4 corner Sec 24) Set qr.Sec Post, Fir 12" N72E 261ks, Hemlock 14"						
S79W 171ks.						
K-9 (SW corner Sec 24) Set Post cor Secs 23,24,25 & 26 from which Hemlock 12" S23W 251ks, Y.Birch 16" N36E 311ks.						
K-10(W1/4 corner Sec 25) Set qr. Sec Post , Sugar 10" S12W 101ks, Maple 6"						
N73E 211ks.	, , , , , , , , , , , , , , , , , , , ,		10 012	, lorke,	napr	- 0
B. Description of corner ev	vidence found and/or method app	lied in restoring or reesi	tablishing corne	er:		
	t intersection of fer					
K-9 Restored at intersection of old wire fence to East and painted line South						
K-10 Restored at 12" W.Pine with Keweenaw Land Assoc. tag and at intersection						
of painted.	line North and East	from corner.		ARREST TO THE	MARKAGE.	ı
		•		SKAN E OF	TICH G	Ne.
			اد	5		
			₹	*/ RONA		Y 3
				PROFES	SIONAL	181
			•	SURVI		jā į
			3	394		Ė.
				40		
				MANOFER	810	Na.
C. Description of monume	nt for comer and accessories esta					
L-9 Set 1" I.D. witnesses:	by 36" pipe	K-9 Set 1"		36" pipe	2	
S59W 2.73' 5	i" Manle	witnes		Maste		
N37W 12.30'			1.03' 10" 9.75' 10"			
S8W 15.02'	16" Maple		3.30' 10"			
N64E 14.88'			3.86' 10"			
·				-		
K-10 Set 1" I.D.	by 36" pipe witness	ses: S30E 13.	52' 10" W	.Pine,		
N38E 0.92'	12" W.Pine, S60W 15.	27' 8"Oak, N4	6W 21.22'	2" Map1	e.	
	1 1/1					
Signed by Konald	S. Flantsia	Date	July 20	, 1995		
	~~ · · · · ·		,			
Surveyor's Michigan License	€ No. 0/7/8	FORM AP	PROVED BY MICHIGAN ST	ATE BOARD OF PROFES		EYORS, JAN. 28, 1971 EVISED MAY 14, 1975