

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

|                                    | <u>Huron</u><br><small>(County)</small> | Located In:     | Corner Code // |
|------------------------------------|---|-----------------|----------------|
| 1. Public Land Survey              |   | T 15N R 14E     | 2-F            |
|                                    |   | T _____ R _____ | _____          |
|                                    |   | T _____ R _____ | _____          |
|                                    |   | T _____ R _____ | _____          |
| 2. Property Controlling in Section | S 4                                     | T 15N R 14E     | 8              |
|                                    | S _____                                 | T _____ R _____ | _____          |
| 3. Miscellaneous Property in Sec.  | S _____                                 | T _____ R _____ | _____          |
|                                    | S _____                                 | T _____ R _____ | _____          |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

I, Donald L. Bissell in a field survey on January, 1989, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

|    | A  | B  | C  | D  | E  | F  | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2  | 6  | 5  | 4  | 3  | 2  | 1  |   |   |   |   |   |   |   |
| 3  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 4  | 7  | 8  | 9  | 10 | 11 | 12 |   |   |   |   |   |   |   |
| 5  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 6  | 18 | 17 | 16 | 15 | 14 | 13 |   |   |   |   |   |   |   |
| 7  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 8  | 19 | 20 | 21 | 22 | 23 | 24 |   |   |   |   |   |   |   |
| 9  |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 |   |   |   |   |   |   |   |
| 11 |    |    |    |    |    |    |   |   |   |   |   |   |   |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 |   |   |   |   |   |   |   |
| 13 |    |    |    |    |    |    |   |   |   |   |   |   |   |

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-2  
 Center Section 4, T15N, R14E  
 Set 4" x 36" conc. mon. with alum. cap at intersection of 1/4 lines.


8  
 N 1/8 Cor. of SW 1/4 Sec. 4, T15W, R14E  
 Set 4" x 36" conc. mon. with alum. cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-2  
 S77°E - 36.15' - 6" Ash  
 S40°W - 26.64' - 8" Ash  
 N81°W - 17.23' - 10" Maple  
 N30°W - 17.67' - 12" Ash  
 North - 32' - E-W fence  
 East - 33' N-S fence

8  
 N11°W - 24.20' - 20" Willow  
 S50°E - 43.40' - 24" Ash  
 S01°W - 42.97' - 34" Cottonwood  
 S84°W - 23.78' - 8" Maple  
 North - 23' - Fence line East  
 North - 12.8' - Old fence cor. post

Signed by Donald L. Bissell Date \_\_\_\_\_  
 Surveyor's Michigan License No. 18655



FOR APPROVAL BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971  
 REVISED MAY 14, 1975  
 REVISED JAN., 1983