Common to:

M01 – Colfax Twp. – T16N-R12E M13 – Meade Twp. – T17N-R22E A13 – Lincoln Twp. – T17N-R13E

Peer group approved at meeting held December 8, 1998. RKB

Re-Mon Lider 1, Pages 233

1998 REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For Corners in VERONA Tow | • | quirement of Act 74 | 4, Mich. P.A. 19 | 70 | | |
|--|---|--|---|---|-----------------------------------|--|
| FOI COMEIS IN VENONA TOW | · | | | | | |
| Huron (County) | Located in: | Corner Code # | SUFNEY NONUMEN | S. TATION | STATE OF MI HURON CO RECORT | JUNTY |
| Public Land Survey | T 16N_R 13E TR TR | A-1 | .IAN 2 3 13 | | 15 DEC 98 3 | |
| in Section — — — | | | | FRANCES L. HOLDWICK REGISTER OF DEEDS | | |
| 3. Miscellaneous S T T | | | | | | |
| Lot No , Recorded Private Claims | Plat | | | 8 C D | E F G H | 2 1 1 1 |
| | | | | 3 4 7 8 5 | 9-10 | 1112 |
| I, Russell L. Brown, in a fiel requirements of P.A. 74, Michiga above were in conformance wit manual of survey instructions of Management or by a decree of lines 3, 4, and 5 above were in Surveyors or by a Decree of recovered, found as expressed to | an P.A. of 1970, the cor th regulations and rules the United States Depa a Court of Law and/or conformance with the a Court of Law; estab | rner points mentioned s therefore as require artment of the Interior, r that the corner poin rules of the Michigar | d in the current Bureau of Land ts mentioned in Board of Land monumented, | 6 — 18 — 17 7 — 8 — 19 — 20 9 — 10 — 29 | 21 -22 -22 -23 -27 | 23 24 25 25 25 25 25 25 25 25 25 25 25 25 25 |
| NOTE: Not more than 2 corr on this certificate. | iers, all in the same to | own and range, may | y be recorded | 13 | | |
| A. Description of original mo 1834 G.L.O. H. Parke D.S County Surveyor Records: County Road Commission Recorded Surveys: Over Unrecorded Surveys: NON | :. Set as A-13, T17N- NONE Records: Monument | -R13E, B. Ash 13 S | 43E 2; Cedar 17 | | e S45°E 42. | 55'; |
| B. Description of corner evid No evidence of original cor | ence found and/or m ner or accessories fo | ethod applied in resound. | storing or reestab | olishing corr | ner: | MICH |
| Found 1" Steel Bar in Mon | ument Box. | | | | , , | SELL L. ALMOWN |
| Accepted found 1" Steel Ba | ar in Monument Box a | as best evidence of | original corner p | osition. | SUR | VEYOR OF SIR |
| C. Description of monument A-1, Northwest corner of S Found 1" Steel Bar in Mon WITNESSES: N45°W 57.02' set 1/2" Steen N45°E 50.40' set 1/2" Steen S65°W 75.50' found Form S55°E 90.60' found Form East 6.90' to centerline of S East 2484.06' to B-13, Sou West 2646.31' to L-13, Sou | ection 6, T16N-R13E ument box el stake at Southeast el Stake Nail & MDOT Tag in Nail & MDOT Tag in N State Trunkline M-53 uth 1/4 Corner Section | Corner Concrete Particle Powers Side Power Sid | ad Ped. Base ver Pole | NOTE: This co A-13, T M-1, T | | |
| Signed by Sussell Surveyor's Michigan License | L Daga No. 24588 | en | Date <u><i>05</i>C,7</u> | 1998 | | |

Leder 1, Page 233 A

Recorded Surveys: A-1 Verona

October 10, 1974, Liber 2, Page 238, by Stewart G. Case P.S. 15399 Southeast Corner Section 36, T17N-R12E, Meade Township; Monument Box 5.0' West of centerline of Highway M-53 No witnesses given;

March 28, 1979, Liber 3, Page 715, by Stewart G. Case P.S. 15399

Northeast Corner Fractional Section 1, T16N-R12E

1" Steel Shaft in place in monument box approximately 5.0' West of centerline of highway right of way. No witnesses given;

Liber 3, Page 760, by Stewart G. Case P.S. 15399
Northeast Corner Fractional Section 1, T16N-R12E,
1" Steel Shaft in place in monument box approximately 5.0' West of centerline of highway right of way.
No witnesses given;

\$ 9.00 SURVEY \$ 2.00 HSSR

SURVEY & REMONUMENTATION

JAN 2 8 1999

SECTION