REMONUMENTATION

JAN 2 2 1998

SECTION

hon. Liber 1, Page 90

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in VERONA TOWNSHIP

HURON (County)	Located in:	Corner Code #			
1. Public Land Survey	T _{16N} R 13 T R T R	BE <u>F-13</u>			
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR				

STATE OF MICHIGAN HURON COUNTY RECORDED

1 DEC 97 1:51 P.M.

FRANCES L. HOLDWICK REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No	Recorded Plat
5. Private Claims	

Brown, in a field survey on Oct. 16,, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	В	С	D	E	F	G	Н	I	J	К	L
2		- 6 		ļ -				Ţ	T	Ţ	T	Ţ
3		Ĺ								-2-		
4		 - 7 _		8		9_	Τ		T	7		
		ĺ	-				7	-10 	1	-11 <u>-</u> 	7	-12
5		T			7	Ţ~~	\top	_	†-	十	$^{+}$	
6	\vdash	-1 8	-	17-	+	16-	+	-15-	╁	-14	+	-1¦3—
7	\vdash	+	-	┼	┼-	┰	- -	+	╀		+	
8	<u> </u>	19—	-	2 <mark>0_</mark>	1	.2 1 —	- -	-22	_	.23 <u>—</u>	<u> </u>	24
9	<u> </u>	<u> </u>	igspace		<u> </u>	\perp	\perp					Ĺ.,
10] 30	ļ	 29	<u> </u>	 2B—	_	 -27—	_	 26	_	 25
1 1	ļ	 	_	<u> </u>	<u> </u> _	↓	_		<u> </u>	1	_	
12		 31	<u> </u>	 32—-	<u> </u>	 33	<u> </u>	 .34—		 35	\perp	 -36
13	<u> </u>	<u> </u>	L,		<u>L</u> ,	<u>.</u>	L					<u> </u>

A. Description of original monument and accessories and/or subsequent restoration:

1834 G.L.O. H. Parke D.S. Set quarter Section Post Hemlock 30 East 23, Beech 18 N38W 24 1/2

COUNTY SURVEYOR RECORDS: None

ACT 74 FORM: None

COUNTY ROAD COMMISSION RECORDS: None

RECORDED SURVEYS: None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original Corner or accessories found. Found 3/4" Dia. Re-rod in centerline gravel road East and West (Popple Road) and in line with Fence North.

Accepted 3/4" Re-rod as the best evidence of original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 1/4 Corner Section 33, T16N-R13E,

Found 3/4" Dia. Re-rod

WITNESSES:

North 34.36' to P.K. Nail in West Side Gate Post

N40°W 48.70' to P.K. Nail in Northeast Side Gate Post

N45°E 50.49' to P.K. Nail in Northwest Side Wood Post

S55°W 108.64' to Nail in North Side Power Pole

East 2639.54' to Southeast Corner Section 33, T16N-R13E

West 2639.54' to Southwest Corner Section 33, T16N-R13E

Signed by <u>Dussell</u> L

MASO LAND S

Surveyor's Michigan License No. 24588

PEER GROUP APPROVED

AT MEETING HELD

NOU 25, 1997. RLB

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

RUSSELL I

BROWN

LAND

SURVEYOR