| Common to: A13 – Chandler Twp. – T17N-R11E A01 – Oliver Twp. – T16N-R11E M01 – Winsor Twp. – T16N-R10E | | | | | |
|--|--|--|---------------------------------------|--|--|
| 1998 REMONUMENTATION LAND CORNER RECORDATION Filing Requirement of Act 74 | | | | | STATE OF MICHIGAN |
| For Corners in Huron Located in: Corner Co | | | Corner Code | # | HURON COUNTY Recorded |
| | unty) | IB v | | | 11 DEC 98 9:42 A.M. |
| Public Land Property Co. | T T T | R 10 E R R R R R R R R R R R R R R R R R R | L-13 M-13 | | FRANCES L. HOLDWICK REGISTER OF DEEDS |
| in Section 3. Miscellaneo | sT | R | · · · · · · · · · · · · · · · · · · · | Register of Deed | s Stamp & File Number |
| 4. Lot No, Recorded Plat | | | | | |
| 1. <u>James T. Meek</u> , in a field survey on <u>October 30</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expessed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded | | | | | |
| on this certificate. | | | | | |
| A. Description of original monument and accessories and/or subsequent restoration: Original Survey South Bdy. T17NR10E, 1835, Harvey Parke, D.S. | | | | | |
| L-13 South & Corner of Section 36 M-13 Post Lynn 8", N39°E, 35 links Elm 9", N33°W, 23 links County surveyors record; none Recorded surveys: none LCRC: none | | | м-13 | Corner of Townships 16 and 17 North, Ranges 10 & 11 East Post B. Ash 22", \$62°E, 36 links Birch 10", \$75°W, 4 links County surveyors record; none Recorded surveys: none LCRC: none | |
| | | | | | |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: | | | | | |
| L-13 South & Corner of Section 36 | | | M-13 | Corner of Townships 16 and 17 North, Ranges 10 & 11 East Found 1" iron in mon box | |
| There of the | There is no remaining evidence of the original corner position. SURVEY & | | | | |
| | REMO | SUMENTATION | energy (| At intersection of Bern | • |
| | JA | N 2 8 1999 | | Accepted as the best av of the original corner: | |
| SECTION | | | | | |
| Description of monument for corner and accessories established to perpetuate locating the position of the corner: | | | | | |
| | | | | Corner of Townships 16 and 17 North, Ranges 10 & 11 East | |
| Set 1/2" iron w/cap #39089 in mon box At proportionate distance | | | | 1" iron in mon box | |
| From which: Tag on power pole N2°E, 49.8' Fence post bears S15°E, 41.8' '' iron bears S45°W, 24.0' '' iron bears N45°W, 22.0' | | | | From which: Concrete row marker bears N54°E, 45.6' Road sign post bears \$26°E, 34.0' Concrete row marker bears \$47°W, 54.1' Tag on power pole bears N65°W, 75.75 (MM) | |
| ■gned by | A ane | | D | ate December 8, 1998 | JAMES T. VAMEEK LAND SURVEYOR |
| □ PROVED AT PEER BOARD MEETING, // -24 - 98 RXB | | | | FORM APPROVED BY MICHIG | AN BOA DO SE LAND SURVEYORS, JAN. 28 44 C. |
| SURVEYOR FORM APPROVED BY MICHIGAN BOARD OF LAND SURVEYORS JAN 28 JAN 2 | | | | | |