A13 – Lincoln Twp. – T17N-R13E AUI - Verona Twp. - T16N-R13E M01 - Colfax Twp. - T16N-R12E

Re-Man Lele	N1,	Page	231
NOO DEBAONII ISSENITA TIONI	•	//	

1998 REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN

Filing Requirement of Act 74, Mich. P.A. 1970 For Corners in MEADE Township					HURON COUNTY RECORDED					
Huron (County)	Located in:	Corner Code #	SURVE	EV S ENTATI	ON	15 DEC	9 8	3:34	P.M	•
1. Public Land Survey	T 17N R 12 T R T R	<u>M-13</u>	.IAN 28		432 1. ()	FRANC REGI		, HOLI OF D		Κ
	T R		SECTIO	MC						
in Section S 3. Miscellaneous S Property in Sec. S	T R T R T R			R	egister	of Deed	ds Star	mp & I	File N	lumbe
Lot No, Recorded Private Claims	Plat			1 A B C	- S	F F	С Н 		2	
				4			10-		' ,	1 ¹ 2
I, Russell L. Brown, in a field requirements of P.A. 74, Michigal above were in conformance with manual of survey instructions of the Manual of Survey instructions of the survey in the	n P.A. of 1970, the c regulations and rul he United States Dej	orner points mentioned es therefore as require partment of the Interior,	in lines 1 and 2 of in the current Bureau of Land	5 6 18 7 8 19	17	16-	15-	1	3	-13
Management or by a decree of a lines 3, 4, and 5 above were in a Surveyors or by a Decree of a recovered found as expressed by	conformance with th Court of Law; esta	e rules of the Michigar	Board of Land	9 30		28-		21	5-	-25-

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

1834 G.L.O. H. Parke D.S., Set as A-13, T17N-R13E, B. Ash 13 S43E 2, Cedar 17 S82W 7,

County Surveyors Records: NONE

County Road Commission Records: Monument Box, 3" Cal. Maple N89°E 58.22'; 8" Cal. Maple S45°E 42.55'


Recorded Surveys: Over Unrecorded Surveys: NONE

on this certificate.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original corner or accessories found.

Found 1" Steel Bar in Monument Box

Accepted Found 1" Steel Bar in Monument Box as best evidence of original corner position.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-13 S.E. Corner Section 36, T17N-R12E

Found 1" Steel Bar in Monument Box

WITNESSES:

N45°W 57.02' Set 1/2" Steel Stake at Southeast Corner Concrete Pad Ped. Base

N45°E 50.40' Set 1/2" Steel Stake

S65°W 75.50' found Form Nail & MDOT Tag in Northwest side Power Pole S55°E 90.60' found Form Nail & MDOT Tag in Northeast Side Power Pole

East 6.90' to centerline State Trunkline M-53

East 2484.06' to B-13, South 1/4 Corner Section 31, T17N-R13E West 2646.31' to L-13, South 1/4Corner Scetion 36, T17N-R12E

Kusull Signed by Surveyor's Michigan License No. 24588

Date 1/EC

Peer group approved at meeting held December. 8, 1998. RAB

NOTE:

This corner is common with

A-13, T17N-R13E M-1, T16N-R12E

A-1, T16N-R13E

Leder, Page 231A

Recorded Surveys

October 10, 1974, Liber 2, Page 238, by Stewart G. Case P.S. 15399, Southeast Corner of Section 36, T17N-R12E, Meade Township, Monument Box 5.0' West of Centerline of Highway M-53,

No Witnesses given:

March 28, 1979, Liber 3, Page 715, by Stewart G. Case P.S. 15399, Northeast Corner Fractional Section 1, T16N-R12E,

1" Steel Shaft in Monument Box approximately 5.0' West of Centerline of Highway Right of Way. No Witnesses given:

Liber 3, Page 760, by Stewart G. Case P.S. 15399, Northeast Corner Fractional Section 1, T16N-R12E, 1" Steel Shaft in place in Monument Box approximately 5.0' West of centerline of Highway Right of Way. No Witnesses given:

j

\$ 9.00 SURVEY

\$ 2.00 MSSR

SURVEY & REMONUMENTATION

JAN 2 8 1999

SECTION