## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	7
1. PUBLIC LAND SURVEY	T S., R E.	:	Ro H
2. PROPERTY CONTROLL- ING IN SECTION 17	,т. <i>18</i> ., r. 12 Е.		
3. MISCELLANEOUS PROPERTY IN SECTION 12	,T. /8 N. R. /2 E.		
4. LOT NO , RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1923, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1923, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
_			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  _Recovered 3/6" Iron With Notes from  CASE Surveying Bad Axe, Michigan			
C. Description of monument for	or corner and accessories	established to perpetuate loc	ating the position of the corner:
3/8" IRON ROD		• •	•
S. 12° W. 13.0 N. 56° W. 6.0 N. 64° F 10.43			
All distances to PA	CONTROLS IN PROCES		
SIGNED BY		date <i>A</i>	ett 26, 1913
SURVEYOR'S MICHIGAN REC			(SEAL)
FOR STATE AND UNITED ST	ATES AGENCIES:		
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	MICHIGAN REGISTERED L	AND SURVEYOR DATE	
			(SEAL)