LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -: LOCATED IN -:	CORNER CODE NUMBER	/ /
1. PUBLIC LAND SURVEY 17 T. 18 N., R. 12 E.	<u>C-5</u>	Hur
2. PROPERTY CONTROLL- 17, T. 18 N. R. 12 E.	C-5	3
3. MISCELLANEOUS PROPERTY IN SECTION, T		
4. LOT NO , RECORDED PLAT		
5. PRIVATE CLAIMS		REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Macch 19 1923, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on Macch 19 23, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law: A. Description of original monument and accessories and/or subsequent restoration:		
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found 4" Sq. Jones. Mon. 3" Below Surface Recovered with Notes by Case Surveying Bad Axe, Mon. Placed Cap = 12029 ON Mon.		
C. Description of monument for corner and accessories of 4" Sq. Conc. Mon. Nith Cap # 120. Narth 79.03" 12" Oak. (N-S) N.65° E. 89.52' 10" Forked. S. 06° W. 44.33' 3" W. Birch S. 32' E. 60.29 5"W. Birch	29 Fonce in tree) Maple	ating the position of the corner:
All distances to Pkinals in signed by Surveyor's Michigan registration no. 120:	DATE	3-19-23
FOR STATE AND UNITED STATES AGENCIES:		
SIGNED BYCHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY	AND SURVEYOR DATE	(SEAL)