## LAND CORNER RECORDATION CERTIFICATE

FILING	REQUIREMENT	OF	ACT	74	MICH		1070
1 161110	MEGOIVEMENT	Or.	$\sim$	/4.	MICH.	F.A	.197 / U

FOR CORNERS OF -:	LOCATED IN -:	CORNER COD	E NUMBER	
1. PUBLIC LAND SURVEY	Z T. <u>18 <sup>N.</sup></u> , R. <u>12 E.</u>			Him 3.
2. PROPERTY CONTROLL- ING IN SECTION	7 ,T. 18 N. R. 12 E.			1/1/
3 MICCELL ANDOUG	7 ,T. /8 N. R. /2 E.			
4. LOT NO , RE	CORDED PLAT			
5. PRIVATE CLAIMS		-		REGISTER OF DEEDS STAMP AND
field survey on Marion restored as expressed below of survey instructions of the court of law. Furthermor March 19 23	19 23; established, and in conformance with regul United States Department of the, that the corner points me, found, recovered, restored, es	re-established ations and rules the Interior, Burgationed in line tablished or re-	es on index, monuments therefore a cau of Land s 3,4 and 5 established	P.A. 74, Michigan P.A. of 1970, code diagram – over) were, in a ed, re-monumented, recovered of s required in the current manual Management or by a decree of a above were, in a field survey or as expressed below and in control or, by a Decree of a Court of
A. Description of original mo	nument and accessories and/o	or subsequent re	storation:	
•				
B. Description of corner evid	ence found and/or method appl	ied in restoring	or re-establ	lishing corner:
Set 34 IRON E	DOE ON line and eq.	unt distra	nde free	m Gorf, Coerrie
C. Description of monument i	or corner and accessories est	ablished to perp	etuate loca	ting the position of the corner:
34 IRON Par 1	with Cap #12029	• •		p promise and connect.
5. 45° W. 51.40				
N. 32° W. 52.74 N. 4° E. 38.63	6" W. Birch			
N. 45° E. 62.40	o G" OAK			
S. 25° E. 35.4	6 5" Maple		•	
All distances is			_	
SIGNED BY			ге <u> </u>	-/9-13
SURVEYOR'S MICHIGAN REC		9		(SEAL)
FOR STATE AND UNITED ST				
SIGNED BY	CHIEF OF SURVEY PARTY	DA	TE	
APPROVED AND SIGNED BY				
				(SEAL)