## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY Z	3 T. 19 N. R. 13 E.	<u>J-9</u>	
2. PROPERTY CONTROLL-	,T		
3, MISCELLANEOUS	, T S., R E W.		
	CORDED PLAT		
			REGISTER OF DEEDS STAMP AND
			FILING NUMBER
the corner points mentioned field survey on <b>Novem</b> restored as expressed below of survey instructions of the court of law. Furthermor	in lines 1 and 2 above (iden 19.79, established and in conformance with regulative States Department of the corner points me found, recovered, restored, e	tified with circles on index, re-established, monument lations and rules therefore a the Interior, Bureau of Landentioned in lines 3,4 and 5 stablished or re-established	P.A. 74, Michigan P.A. of 1970, code diagram — over) were, in a ed, re-monumented, recovered or as required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in contrast or, by a Decree of a Court of
A. Description of original monument and accessories and/or subsequent restoration:			
J-9 Found 9/8" ro of Pt. Aux B road.	dence found and/or method ap	ion Mace	
J-9 N 27°W-5 N 18° E - 12	5.55'- Power Po 21.27'- 14" Ask 15'- Guy Poke	le, spike & tay	cating the position of the corner:
SIGNED BY		DATE _	
SURVEYOR'S MICHIGAN R	EGISTRATION NO =		(SEAL)
FOR STATE AND UNITED			<u> </u>
SIGNED BY	CHIEF OF SURVEY PARTY	DATE -	
APPROVED AND SIGNED I		T > 4 (T) T :	(SEAL)