The state of the s
SURVEY PEER GROUP AS THE OFFICE
OF A 1990 ATO A MEETING HELD ON
- C C
AL RINGENBERG, CD. REG

For corners in

LIBER 3 PAGE 227 REMONUMENTATION

128'728 RECORDED HILLSDALE CO. MICH.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'97 NOV 26 PM 4 07

Quela	Vanzandt FDEEDS
$\mathcal{L} = \mathcal{L}$	()
7 EFC. 0	FDEEDS

 HILLSDALE (County)
 Located In:
 Corner Code ##

 Public Land Survey
 T 6S R 1W G-7
 T R ...

 T R ...
 T R ...
 T R ...

 Property Controlling
 S T R ...
 T R ...

SURVEY & REMONUMENTATION


FEB 1 1 1998

Register of Deeds Stamp & File Number

"	Property Controlling in Section Miscellaneous Property in Sec.	S T _ S T _	R R R R	F
	Lot No, Private Claims,	Recorded Plat _		

I. <u>Jeffrey A. Bieszk</u>, in a field survey on <u>12 November</u>, 19 <u>97</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



AC. Description of original monument and accessories and/or subsequent restoration:

GLO set by Robert Clark Jr. (1824) 12" Hickory N 86 E 14 lks 5" Ironwood S 51 W 21 lks LCRC (Maurice H. Mahieu L 604, P 624)
Nail 24" Walnut S 12 E 110.30 ft.
Nail Utility Pole S 13 W 178.83 ft.
Nail 12" Walnut S 88 W 41.88 ft.
Nail R.R. tie fence post N 84 E 29.89 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Mahieu found 1/2" rod in centerline of Road. Rod was used by other area surveyors. He accepted iron. I found iron as witnessed by Mahieu, dug under iron found nothing, and accepted as the best available evidence of the position of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box

Nail w/tag fence post N 87 E 29.73 ft.
Nail w/tag Twin Hickory N 12 E 118.00 ft.
Nail w/tag 14" Walnut S 85 W 42.12 ft.
Nail w/tag 22" Walnut S 10 E 110.65 ft.



Signed by

_____ Date 25 November (797