RECORDED

## LIBER 3 PAGE 253

HILLSDALE COUNTY REMONUMATION CORNER ILLSDALE CO. MICH. LAND CORNER RECORDATION CERTIFICATE 88 AUG 7 AM 10 10 Filing Requirement of Act 74, Mich. P.A. 1970

	y itequireme	it of Act 14, mion. : .A. i.	J10	
For corners in		1	0 = 11	anzandt DEEDS
•			Arregri.	0
HILLSDALE COUNTY Locat	ed in:	Corner Code	O SECOPE I	rfnŠ
ADAMS TWP.			KEG. OF E	, , , , , , , , , , , , , , , , , , , ,
		l		
1. Public Land Survey T 6 S	B 2 W	G-7		
•				
<del></del>	₹			
T F	₹			
T F	₹			
<del></del>	3			
	`			
in Section S				
T R	***	SURVEY &		ds Stamp & File Number
3. Miscellaneous S	R	EMONUMENTATION		
T R				
Property in Sec. S		FEB 2 3 1999		
T R				
		~ F ~ T & A & &		
		SECTION		
4 1 - t No. Donnal Diet				
4. Lot No, Recorded Plat			ABCDE	FGHIJKLM
5. Private Claims			_	_
			2 - 6 - 5 - 1	
			3	
			4	_ 91'01'11'2
I FRIMADD W DEED :- Fold our or		26 10 00	5	
I, EDWARD W. REED , in a field surve			6 -18-17	15 14 13
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points				
mentioned in lines 1 and 2 above were in conform				
required in the current manual of survey instructi Interior, Bureau of Land Management or by a deor	uns or the Unit	ed States Department of the	8 -19 - 20	-21-22-23-24-1
			9	
points mentioned in lines 3, 4 and 5 above were in Board of Land Surveyors or by a Decree of a			10 30 29	28 27 26 25
monumented, recovered, found as expressed below		, databasiled, to carabilistica,		
monumented, recovered, round as expressed below	•		11	
NOTE: Not were then 2 something in the come to		may be recorded	12 31 32	_3'33'43'53'6
NOTE: Not more than 2 comers, all in the same t	Own and range,	may be recorded	13	
on this certificate.			13	
CORNER COMMON TO SECTIONS 15-16	i-21-22			
A. Description of original monument and acc	essories and/o	r subsequent restoration:		
·		·		
1973: ROBERT BURRIS, SR., SURVEYOR- FO	UND IRON PIP	E SET 1" IRON OVER EXIST	TING IRON, RECOR	DED IN
LCRC LIBER 1, PAGE 301	OND INON III	2, 321 1 111011 0 1211 2210	ring mon, meson.	
LCRC LIBER 1, PAGE 301				
B. Description of corner evidence found and	dia mathad an	ntind in rectaring or reactable	iobina gornari	
B. Description of corner evidence found and	Joi metrioo ap	phed in restoring or reestable	isimiy comer.	
FOUND IDON DOD INCIDE OF AN V 41 LONG	DIDE NO OTH	ED ELVIDENCE COURS		
FOUND IRON ROD INSIDE OF 1" X 4' LONG	PIPE, NO OTHI	ER EVIDENCE FOUND.		
			•	
<ul> <li>C. Description of monument for corner an</li> </ul>	d accessories	established to perpetuate loc	ating the position o	f the corner:
REMOVED IRON PIPE, SET 3/4" X 30" REBAR	R IRON WITH R	REMON CAP IN CI-MONUME	NT BOX, 4" BELOV	V GRAVEL ROAD
SURFACE.			·	
DE NATI ME CIDE OF DATEDLACK LOCHET	NODTIL	21.00!		OF MICH
PK NAIL W. SIDE OF 24" BLACK LOCUST,		31.82'		F. 1
PK NAIL SE SIDE POWER POLE,		42.73'		EDWARD *
WEST END ROAD CULVERT,		27.7'	•	W. REED
EAST END ROAD CULVERT,	N 15 E	20.6'		LAND
SW CORNER HOUSE	N 40 W 1	53.2'		SURVEYOR
			•	NO. S
				33985
AND IS ACCEPTED AS THE BEST AVAILABLE	E EVIDENCE O	E THE POSITION OF THE OF	RIGINAL CORNER	
THE TO ACCEL TED NO THE BEST AVAILABLE			COINE	SED LAND SUR
				AND SOUTH PROPERTY.
Simular Mar. MIN	11		Data.	AUGUST 5 1000
Signed by Alle 101	7		Date	AUGUST 5, 1998
EDWARD W. REED				
Surveyor's Michigan License No	33985			
Odiveyor o mionigan Election No.				