

Frederick J. Cutcher Surveyor's Michigan License No.

24592

## LIBER 3 PAGE 93 HILLSDALE COUNTY REMONUMENTATION

## 107579 PEGORDED

## LAND CORNER RECORDATION CERTIFICATE

PILLODALE CO. MICH.

Ερι	r corners in	Filing Requir	ement of Act 74, Mich. P.	195 DEU 15 PM 1 03
. 01	Hillsdale	Located In:	Corner Code ##	0 5 11 3 5
	Fayette Twp.	Located III.	Comer Code -44	Judy Vanzands
1	Public Land Survey	T 6 S R 3 W	G-3	REG. OF DEEDS
•	Fublic Land Guivey	T R		
		T R	11 AND THE RESIDENCE AND THE PROPERTY OF THE PARTY OF THE	COLVAENTATION
_		T R	A AND A AND A AND AND AND AND AND AND AN	Control of the Contro
2.	Property Controlling in Section	S T R S T R		JAN 3 0 1996.
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
•	Property in Sec.	S T R		COMMISSION
4	Let No. D	ecorded Plat		
		ecolued Flat		A B C D E F G H I J K L M
				2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
	; 			3 + + + + + + + + + + + + + + + + + + +
	Frederick J. Cutcher	in a field survey on Nove	mher 21 19.95	5 7 8 9 10 11 12 12 13
do	hereby certify that under reg	uirements of P.A. 74, Michigan P.A	of 1970, the corner points mentic	ned 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
in I	lines 1 and 2 above were in	conformance with regulations ar	nd rules therefore as required in	the , The lift is a second of
CUI Ma	rrent manual of survey instru	ictions of the United States Depart Court of Law and/or that the corne	tment of the Interior, Bureau of L economy mentioned in lines 3, 4 a	and
abo	ove were in conformance wit	h the rules of the Michigan Board	of Land Surveyors or by a Decree	ofa
		e-established, monumented, re-	monumented, recovered, found	1 as 10 30 29 28 27 26 25
	oressed below:	orners, all in the same town a	nd range may be recorded	11
NC	on this certificate.	orners, all in the same town a	na range, may be recorded	12 31 32 33 34 35 36
			•	13
Α.	Description of original monument and accessories and/or subsequent restoration:  Fayette.Twp.  Corner common to Sections 3, 4, 9 & 10, Town 6 South, Range 3 West.			
			_	•
	Original Government Survey, 1825, Robert Clark, Jr.: W. Oak 20 in., N. 35° W., $19\frac{1}{2}$ ; B. Oak 11 in. N. 83° E., $29\frac{1}{2}$ .			
	Survey No. 1095, June 4, 1889, R.J. Coryell: Est. iron; Hick. 12" N. 86° E.			
		Sub. (L7/P5 Plats); Na	il S. side 12" Cherr	iron pipe as used for cor. y E., 33.15'; Nail W. side
B. Description of corner evidence found and/or method applied in restoring or reestal				blishing corner;
	Found 1" iron pipe in the intersection of the remains of fence/stone row.			
	Found stump of on	ne of above references	•	A BRIDGE
	-			A PER OF MICH
			•	* FREDERICK IN A
	•	•		CUTCHER V
	•			PROFESSIONAL SURVEYOR
				7 No. 12 24592
				24592
				OFESSION AND THE STATE OF THE S
		•	,	ESSION AND THE PROPERTY OF THE
	•	•		
Ç.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:  Set 3/4"x36" iron rod with cap (County issue) inside iron pipe found and is accepted as the best available evidence of the position of the original corner. Set steel fence post on South side.			
	P.K. W. side R.R.	e row to North. Hickory S. 60° W., 13 tie cor. post S. 37° Hickory South, 12.35'	E., 52.24'.	
		lickory North, 26.63'.		

Date December 5, 1995