LIBEER 3 PAGE 14

Carrie and the

10

12

#FOORDED 88316 MILLUDALE CO. HICH.

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'93 DEC 22 PM 2 19

For corners in									(\	15	١	١		3				
HILLSTOADE)		Located In:		ed In:	Corner Code ##			Glussy Vonzandt REG. OF DEEDS											
1.	Public Land Survey		T	6s-R _ 3w R R	<u> </u>	G-13 ;							-						
2.	Property Controlling		T	R R R															
3.	Miscellaneous Property in Sec.	s	т	R				Registe	r of	De	eeds	Star	np 8	Fil	e Nı	ımb	er		
4. 5.	Lot No	, Recorded	d Plat						A E	₃ (СВ	E	F G	<u>; н</u>	1	J	ĸ	<u> </u>	
) I						3	6 7	-	5- 		9	-3- -10-		-11		12-	
do in	John E. Maxs hereby certify that under a lines 1 and 2 above were rrent manual of survey ins	requiremen e in conform	its of P.A. 7 nance wit	^r 4, Michigan P h regulations	A. of 197 and rule	70, the corner poi es therefore as re	ntsmentione equired in th	d e	1		17	1	6	15 15		14-		13	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration:

G-13

expressed below:

GLO, 1823, 11 Beech, N50W, 6 1ks

6 Beech, N58E, 15 1ks

Co Sur 1871, Stone

Stone iron, N45W, 70.5 lks

14 Butternut, S20E 106 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Iron and Accepted as the best available evidence of the position of the original Corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13 Reset 5/8 x 36 rebar w/cap in mon. box N41E 50.921 34"Maple S35E 40.94' 30"Maple 575₩ 113.04' 40"Maple N14W 109.01' P.Pole N73E 26.94 30"Maple East 53.46 1/2"rebar

_ Date 22 December, 1993



Signed by .

Surveyor's Michigan License No. ____27454

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971