

1993

LIBER 3 PAGE 13

COMMISSION ON REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED 88315 HILLDALE CO. MICH.

'93 DEC 22 PM 2 19

Judy VanZandt REG. OF DEEDS

For corners in

Table with columns: Located In, Corner Code #, and rows for Public Land Survey, Property Controlling in Section, Miscellaneous Property in Sec., Lot No., and Private Claims.

Register of Deeds Stamp & File Number

Grid table with columns A-M and rows 2-13, containing numbers 1-36 and corner markers.

I, John E. Maxson in a field survey on 22 December, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Table with 3 columns (I-11, I-12, I-13) listing monument descriptions like 'GLO, 1823, 30 Oak, N32W, 27 lks' and 'LCRC, 1981, Ringenberg L2, P42 Iron in Mon. Box'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Table with 3 columns (I-11, I-12, I-13) listing evidence descriptions like 'Found iron from Ringenberg LCRC and accepted as the best available evidence of the position of the original Corner'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Table with 3 columns (I-11, I-12, I-13) listing monument details like 'reset 5/8 x 36 rebar with cap in mon. box' and 'N40E 41.90' THydrant'.

Signed by [Signature] Date 22 December, 1993 Surveyor's Michigan License No. 27454

