1993

LIBER 3 PAGE 29 COMMISSION

\_ , Recorded Plat .

FRORDED 11: DALE CO. MICH.

4. Lot No.

5. Private Claims \_\_\_

**REMONUMENTATION** 

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

'93 DEC 27 PM 3 38

or corners in		i milig residence of Not 7-4, milion i sin for		Judy Vanjands
	HILLSDALE '	Located In:	Corner Code =##	
	(County)			REG. OF DEEDS
	Public Land Survey	7s 3w T R	G-1, I-1,	
		, T R T R		
		T R		
2.	Property Controlling	S R		
	in Section	\$ T R	· <del></del>	
<b>3</b> .	Miscellaneous	S RR		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		

in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, 1823, 30 Oak, S64W, 59 1ks 22 Sugar, S32E, 114 lks GLO, 1823, 24 Elm, S08E, 17 1ks 14 Beech, S31W, 40 1ks

LCRC, 1988, Ringenberg, L575, P214 Rebar

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: I-1

Found iron from Ringenberg LCRC and accepted as the best available evidence of the position of the original Corner

Found Iron at record offset and accepted as the best available evidence of the position of the original Corner

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

reset 5/8 x 36 rebar with cap reset 5/8 x 36 rebar with cap 18.00' N10E 15"Maple South 12.97' 20"Maple NO5W 14.76 15"Maple East 17.80% 18"Tree 43.68' S25E 30"D.Maple 52.67' West P.Pole 525W 40.501 24"Maple East 3.81' Fence Post West 53.46' G-13 @ T6S-R3W West 64.68' I-13 @ T6S-R3W

Date 27 December, 1993

Signed by Surveyor's Michigan License No. \_\_

FORM APPROVED BY MICHIGAN STATE BUARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

MICH/6

JOHN E.

MAXSON

SURVEYOR

No.

LO LAND

REVISED JAN., 1983

