LIBER 3 PAGE 220

REMONUMENTATION HILLSDALE

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

128167

RECORDED HILLSDALE CO. MICH.

'97 NOV 12 AM 9 08

For comers in								
HILLSDALE (County)	Located In:	Corner Code #		Quit	ing U	کیسرگر ا ۱	pure	7
1. Public Land Survey T7S R3W I-13 T R				SURVEY & REMONUMENTATION				
Property Controlling in Section Miscellaneous Property in Sec.	S TF S TF S TF	\$		Register of	EB 1 1			mber
Frederick J. Cutcher requirements of P.A. 74, Michi conformance with regulations at United States Department of the that the corner points mentione Board of Land Surveyors or recovered, found as expressed	, in a field survey or gan P.A. of 1970, the co nd rules therefore as requi e Interior, Bureau of Land ed in lines 3, 4 and 5 abov by a Decree of a Court below:	n 11/7, 1997 do hereby a rer points mentioned in lines 1 and 2 ired in the current manual of survey ins Management or by a decree of a Cour re were in conformance with the rules of Law; established, re-established with and range, may be recorded	2 above were in structions of the rt of Law and /or of the Michigan , monumented,	A B C D 2 6 5- 3 4 7 8- 5 6 18 17 7 8 19 20 9 10 30 29 11 12 31 32- 13	9-16-16-1-1	H I	J K	12—13—13—24—25—25—25—25—25—25—25—25—25—25—25—25—25—
A. Description of original noriginal Govern Elm 30" N. 44°	ment Survey by	ories and/or subsequent restorate William Brookfield,	on: 1825: Ash 1	1" N. 67°	W. 18]	lks.;		

Notes of Ringenberg, A.J. Hatt, 2/24/59: 1/4" iron centerline M-99 West 45.6'; Top cor. fnc. post N. 5° E. 35.8'; pwr. pole N. 40° E. 40.2'.

Notes of Ringenberg, 1/16/67: Fd. 1/4" iron, raised with 3/4" iron pipe from above witnesses. Centerline M-99 West 45.6; P. pole N. 37° W. 40.50; 18" Elm S. 25° W. 107.51; Tel. marker S. 76° W. 90.43; 20" Walnut N. 55° W. 79.54; N.E. Sec. cor.

B. Bescription of corner evidence found and/or method applied in restoring or reestablishing corner: On 9-16-97 I found a 1/4"x12" iron rod in centerline Squawfield Road 44' East of centerline Hillsdale Road.

Two witnesses were found.

Ų.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: On 11-7-97 I replaced the 1/4"x12" iron rod with a County remonumentation bar with acap in monument box and is accepted as best available evidence of the position of the 🦸 original corner.

In centerline Squawfield Road. 44' East of centerline Hillsdale Road.

S.E. cor. 7th guard rail post (from North) N. 25° E. 19.40' N.W. cor. 7th guard rail post (from South) S. 15° E. 18.60' Top cen. tel. stan. S. 72° W. 101.60'

N.W. cor. guard rail post (E. most post) S. 74° E. 93.42'

Signed by AMBULL Surveyor's Michigan License No. Frederick J.

Date 11/10/97

HEDERICK J CUTCHER PROFESSIONAL ਨ SURVEYOR 24592 POFESSION