LIBER 3 PAGE 274

ACCEPTED BY THE HILLSDALE COUNTY SURVEY PEER GROUP AS THE OFFICIAL CONNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 ATTAM MEETING HELD ON OF 1990 ATTAM MEETING HELD ON AL RINGENBERG, CO REP

HILLSDALE COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'98 NOV 25 AM 9 59

For corners in				Lilve Eur	(_) (_v	-, >011	dr
HILLSDALE COUNTY	Located In:	Corner Code #		interior de la constantial del constantial de la constantial de la constantial de la constantial de la constantial del constantial de la c	: OF DEE	U DS	
WOODBRIDGE TWP (County)	•		SURV				
1. Public Land Survey	T <u>8\$</u> R <u>3W</u> TR	J-7	REMONUM		4		
	T R T R		FEB 23	1999			
2. Property Controlling S in Section S 3. Miscellaneous S	_ TR _ TR		SECTI	ON			
Property in Sec. S	_ TR		Penis	ter of Deeds	Stamn & I	File Nun	nher
4. Lot No, Recorded Pl	lat		A B	CDEF	G H 1	I J K	L.
5. Private Claims			z - 6-	5-4-		-2-	<u> </u>
			3 4 7 -		10	11	
I, EDWARD W. REED	in a field survey o	on OCTOBER 26 . 19 98	- 1			Ī	
hereby state that under requirements	of P.A. 74, Michigan	P.A. of 1970, the corner	points	17 16	1 1	14	12
mentioned in lines 1 and 2 above we				1	15		_13-
required in the current manual of survey instructions of the United States Department of the Interior Bureau of Land Management or by a decree of a Court of Law and /or that the corner points				30 31	32	. 33	
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented				1 1			_24-
recovered, found as expressed below:	Court of Law, catabile	nou, re-established, monuni					
MOTE: Not may them 2 compare all in	dh		10 30-	_ 	1 27	26 -	25
NOTE: Not more than 2 corners, all in on this certificate.	the same town and range	e, may be recorded	11			7.5	1
			1231	32 33	34	35-	—36-
QUARTER CORNER COMMON TO	O SECTIONS 14 & 23	3	13			<u> </u>	
A. Description of original monumer	nt and accessories and	or subsequent restoration:	:				
1825: GOVERNMENT SURVEY, C							
4070 D DILLADD CO CUDYCY	OU - OCCK FOR COP	AITTS					

1873: R. BULLARD, CO SURVEYOR - ROCK FOR CORNER

1966: A.J. HATT, SURVEYOR - NOTES INDICATE FOUND STONE, PLACE IRON PIPES HORIZONTALLY ON TOP

1974: D. OLMSTEAD, SURVEYOR - UNABLE TO LOCATE STONE, RESET CORNER FROM PRO RATED RECORD DISTANCE AND OLD ESTABLISHED FENCE LINES, RECORDED IN LCRC 5179

B. Description of corner evidence found and/or method applied in restoring or reestablishing comer:

FOUND OLD STONE (3' X 3') WITH IRON PIPES OVER TOP, ALSO ½" X 18" BOLT ALONG SIDE WITH FLAGGING AS DESCRIBED BY HATT.

ALSO FOUND IRON AS DESCRIBED BY OLMSTEAD AS WITNESS IN LCRC 5179 3.85 FEET EAST OF STONE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 3/4" IRON ROD WITH REMON CAP IN CI-MONUMENT OVER STONE AS FOUND BY HATT, SET MONUMENT BOX 4" BELOW GRAVEL ROAD SURFACE

18" WALNUT N 05 E 33.45 TO PK NAIL WEST SIDE **POWER POLE** SOUTH 78.54 TO TAG ON W SIDE **POWER POLE** N 33 E 90.72 TO TAG ON W SIDE STEEL ANGLE IRON POST SOUTH 23.25' TO NEAR FACE **NW CORNER HOUSE** 103.33' S 56 E OLMSTEAD IRON (LCRC) **EAST** 3.85 SOUTH 0.80

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Surveyor's Michigan License No. 33985 EDWARD R. REED

EDWARD
W. REED
LAND
SURVEYOR
NO.
33985
CO LAND SURVEYOR

Date NOVEMBER 9, 1998