LIBER 3 PAGE 303 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

.,,	7-1 Page 10-1	0712	- 00	- 1-11	υп.
98	DEC	4	AM	11	48

For corners in	F	or	co	rn	ers	İſ
----------------	---	----	----	----	-----	----

4. Lot No. _

5. Private Claims

HILLSDALE (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>8S</u> R_ TR_ TR	4W
2. Property Controlling in Section3. Miscellaneous Property in Sec.	S TR_ S TR_ S TR_	

SURVEY & REMONUMENTATION

FEB 2 3 1999

Register of Deeds Stamp & File Number

Jeffrey A. Bieszk		25 NI	00	•
1	in a field survey on	<u>Z3 NOV</u>	. 19 <u>98</u> do	hereby state that under
requirements of P.A. 74, Michigan	P.A. of 1970, the corr	ner points mentic	oned in lines	1 and 2 above were in
conformance with regulations and ru	ules therefore as requir	ed in the current	manual of e	Unvey instructions of the
United States Department of the Inti-	erior Bureau of Land !	Management or k	Wa daaraa	for Court of Laws and for

that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

, Recorded Plat

1	A 3	<u> </u>	D	Е	F (G :	H	I	J_	K	L	М
1			- 1		1	'			Г	Ţ		
2	<u></u> ⊢ 6	-+	— <u>\$</u> —	+	4-	 —	ģ—	-	<u> </u>	+-	· į –	_
3	-	_		-	ļ	1	ļ	<u> </u>		<u> </u>		
4		\dashv	— 8	+	 9	<u> </u> -;	ļ 10—	-:	 1—	┼	12-	4
5	-		-	╁			<u> </u>	-		-	ŀ	-
6	— i¦e		-17-	1	6—	1	ا ا _ب 5—	<u> </u>	 4—	4	ا 1 _. 3	_
7	-			-		ļ	<u> </u>	<u> </u>	_	<u> </u>	-	_
8	-19	-	20	<u> </u> -2	1	<u> </u>	 ?2—•	_ _2	l 23—	 :	 2 <u>4</u> —	4
9	1	-	\perp	 			_			1	ļ	4
10	30		-29-	2	58——	<u></u> 2	 !7	<u></u> 2	 6		ĺ 25—	4
11		- -	+	 			_	_		-	-	\dashv
12	—3 ¹ 1·		_32	з	3	—3	4	3	5—	 	ا 36—	4
12			ļ	1								1

A. Description of original monument and accessories and/or subsequent restoration:

GLO

Post

5" Oak N42W 42 lks

7" Elm N73E 15.5 lks

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found remains of a fence running West dug along fence to I found remains of fence running North and South, dug around until I found original fence corner. Than I found pieces of small rocks with no evidence of rocks really being in the area around. Accepted post as the best available evidence to position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box

Nail & Tag 12"Ash N 10 E 28.26 ft.

Nail & Tag 8" Ash N 80 E 15.68 ft.

Nail & Tag 24" Twin Ash South 24.10 ft.

Nail & Tag 12" Twin Ash N 70 W 8.53 ft.

Signed by

Surveyor's Michigan License No.