LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	∠ т. <u> </u>	C-11	
2. PROPERTY CONTROLL- 3	<u>'</u> ,TE.	C-11	
	,T		
4. LOT NO, RECORDED PLAT			
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on <u>SEPT 26</u> 1923, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on <u>SEPT 26</u> 1923, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
RECOVERED 12" IRON ROD			
Found Evidence of 4' Sq. itals appears bender in Bingers With 12" IRON Rod in contra of role			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
1/2" IRON Rod			
N. 88° W. 31.00			
East 30.00'			
S. 26° W. 77.8.	B' 7"B. OAK		
S. 25° E. 50.8	4 42 B.OAK		
S. 78° E. 50.3	6 22" B. OAK		
		DATE	
	EGISTRATION NO. 120		
FOR STATE AND UNITED STATES AGENCIES:			
		DATE	
SIGNED BY	CHIEF OF SURVEY PARTY		
APPROVED AND SIGNED BY	MICHIGAN REGISTERED LA	NO SURVEYOR DATE	(SEAL)