## DEC 1 2 1997

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Liber

9 Page 275

For corners in LESLIE TOWNSHIP			FILED
INGHAM COUNTY	Located In:	Corner Code #	970047745 12/02/1997 13:38:17
1. Public Land Survey	T <u>IN RIW</u> TR TR		REGISTER OF DEEDS Paula Johnson INGHAM COUNTY,MI
Property Controlling     in Section     Miscellaneous	S TR S TR		
Property in Sec.	S		Register of Deeds Stamp & File Number
of P.A. 74, Michigan P.A. of 1970 with regulations and rules there. States Department of the Interior that the corner points mentione Michigan Board of Land Survemonumented, recovered, found a	survey on September 23, 1997  If the corner points mentioned in the current manner of Land Management of the lines 3, 4 and 5 above we sayors or by a Decree of a Corner of the corner o	do hereby state that under requirements lines 1 and 2 above were in conformance anual of survey instructions of the United or by a decree of a Court of Law and for in conformance with the rules of the urt of Law; established, re-established,	5
<ul> <li>A. Description of original monument and accessories and/or subsequent restoration:</li> <li>1. NO CORNER WAS SET AS A PART OF THE ORIGINAL GOVERNMENT SURVEY.</li> </ul>			11
2. COUNTY SURVEYOR A. ON MONUMENTATION SHOW	TACKSON IN VOL. 1, PAGE 11 IN. THE REPORT SAYS THAT	3 ON JAN. 16, 1843 USED CORNER. THE CORNER IS IN A SWAMP.	131, 4 3 1 1 3, 1 3 1 1 1 1 1 1 1
LESTER/GARY D. LESTER P	IBER 6, PAGE 129, DATED D S. #18998/17624. "INVEST ACROSS A POND. CORNER OF PHYSICAL LOCATION OF COL	HUATION REVEALED EXCAVATION OF	TE TO BE FUTILE AND UNSAFE AS LOCATION OF IDWAY BETWEEN K-1 AND M-1 LESLIE ON THE RLINE OF PLAINS ROAD AND ±7.0' WEST OF A

FENCE LINE SOUTH. MEASURED EAST 2680.10' TO M-1 LESLIE AND WEST 2680.09 TO K-1 LESLIE. MEASURED EAST TO L-13 VEVAY 36.55'. INVESTIGATION CONDUCTED BY INGHAM COUNTY SURVEY AND REMONUMENTATION PROJECT STAFF. SET 4"X36" CONCRETE MONUMENT WITH 1/2"X38 REPOD AND CAP #18998 IN LOCATION OF CORNER DESCRIBED ABOVE:

NAIL & TAG #18998, WEST SIDE POWER POLE, ENE, 139.09' NAIL & TAG#18998, SOUTHWEST SIDE 8" ELM, ENE, 174.99" NAIL & TAG#19889, NORTH EDGE ROAD SIGN, SSW, 17.55' NAIL & TAG#18998, EAST SIDE 10" TWIN ASH, SOUTH 18.77" 1/2" IRON BAR, L-13 VEVAY, T2N, T1W, EAST. 36.55"

(Continued on back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 1/2" IRON ROD & CAP #18998 ±2" NORTH OF CENTERLINE OF PLAINS ROAD. NO WITNESSES FOUND. DID NOT EXCAVATE AREA DUE TO EVIDENCE OF PRIOR EXTENSIVE FILL ACTIVITIES. REPLACED 1/2" IRON WITH 3/4" IRON ROD WITH CAP STAMPED PA 345, PS28414. SET MONUMENT BOX OVER IRON, THE POSITION OF THE 1/2" IRON ROD APPEARS TO BE THE SAME POSITION AS THE CONCRETE MONUMENT SET BY R.M. LESTER IN 1980. THE POSITION OF THE LESTER CORNER IS THE CORRECT POSITION FOR A LOST CORNER AND THIS SURVEYOR AGREES WITH THE POSITION

C. Description of monument for corner and accessories established to 3/4" x24" iron rod set in the position of the found ½" iron rod; witnesses Nail & tag #28414, northwest side power pole N81°E, 139.34 feet Nail & tag #28414, north side 8" Elm, S80°E 236.56 feet South edge "NO STOPPING, STANDING, PARKING" ROAD SIGN 3/4" iron rod with cap #28414 (L-13, Vevay Twp.) East 36.56 feet		MAURICE H. PROFESSIONAL SURVEYOR
Signed by Maurice Hollander Surveyor's Michigan License No. 28414	Date 10-10-97	No. 28414 SHIP OF ESSIONAL SHIP IN THE SHI

REVISED MAY 14,1975

P.A. 345 INGHAM COUNTY PEER APPROVED 9/25/97 M

REVISED JAIL, 11 REVISED OCT. 11 L-1, LESLIE PAGE 2

## SECTION A, CONTINUED

- 4. An Act 132 Survey recorded in Liber 6, Page 548 on November 28, 1990, by Ron Helsel, P.S. #18994 performed a survey in the Northwe 1/4 of Section 1. Used the same information as A-4.
- 5. An Act 132 Survey recorded in Liber 7, Page 785 on May 10, 1996, by Ronnie M. Lester, P. S. #18998 performed a survey in the Northwe 1/4 of Section 1. "Set ½" bar and cap #18998 2.0 feet north centerline of Road. Corner reset at location established in Liber 6, Page 129 December 1980. Set galvanized nail and 1 1/4" brass tag stamped "18998 LESTER" S.W. side dead 12" elm mag. Az. 88°, 175.29'; Set galvanized nail and 1 1/4" brass tag stamped "18998 LESTER" South side westerly 14" oak of double oak mag. Az. 92°, 247.30'; ½" bar and orange "Polaris" traverse cap mag. az. 355, 10.60'; ½" bar and cap "18998" L-13 Vevay mag. Az. 97, 36.55'; distance to K-1, Leslie Twp. 268/feet"

LITTE