DEC 1 2 1997

Surveyor's Michigan License No. 28414

## LAND CORNER RECORDATION CERTIFICATE

COMMISSION	Filing Requ	uirement of Act 74, Mich. P.A. 19		9 Page 282
For corners in COMMISSION LESLIE TOWNSHIP INGHAM COUNTY	Located In:	Corner Code #		FILED 9/0047749
1. Public Land Survey	T_1N_R_1W_ TR TR TR	<u>M-2</u>	REG P	197047749 1871997 13:38:24 ISTER OF DEEDS Paula Johnson ISHAM COUNTY, MI
2. Property Controlling S in Section S S Property in Sec. S	T R T R T R T R T R		Register of	Deeds Stamp & File Number
4. Lot No, Recorded Plants	al		y B C D	E P G H I J K L
I, Maurice H. Mahlau, in a field survey of P.A. 74, Michigan P.A. of 1970, the conwith regulations and rules therefore as restates Department of the Interior, Bureau that the corner points mentioned in lines Michigan Board of Land Surveyors or monumented, recovered, found as express	on September 15, 1997 oner points mentioned in the current may of Land Management of 3, 4 and 5 above wereby a Decree of a Cou	do hereby state that under requirements ines 1 and 2 above were in conformance nual of survey instructions of the United or by a decree of a Court of Law and for e in conformance with the rules of the	3	16 - 15 - 14 - 13
NOTE: Not more than 2 comers, all is on this certificate.	n the same town and ra	ange, may be recorded	8 19 20 9	21 22 23 24
A. Description of original monument 1. ORIGINAL G.L.O. CORNER WAS SET POST; B. OAK N28 1/2W 32, TAM 8	BY JOSEPH WAMPLER D	Vor subsequent restoration: D. S. IN MAY 1825 *40.00 SET 1/4 SEC.		33 34 35 36
2. COUNTY SURVEYOR A. JACKSON DID 113. NO MENTION OF CORNER MATERIAL S76W 27.1/2 LKS" (THIS INFORMATION V VOL 4A, PAGE 112 TO 1979 CETA FIEM	L, WITNESSES: "B. OAK VAS TRANSCRIBED FROM	K 9 N28 1/2W 32 LKS, TAMARACK 8  A COUNTY SURVEYORS RECORD IN		
(See Back for continuation)				
B. Description of corner evidence to FOUND 1/2" SMOOTH IRON PIPE WITH FOUND THE FOLLOWING WITNESSES: 45.3". 1/2" PIPE IN GOOD CONDITION A investigation of corner by Richard	YELLOW CAP (UNREAD : NAIL & TAG #25832, AND LEFT IN PLACE. A	, west side 32" Walnut, \$14°E, 9 accepted position of ½" pipe as the	ECTION OF KELLY . 1.73'; CENTERLINE	: 18" Hickony, N59°E,
	·			
C. Description of monument for corn 1/2" SMOOTH IRON PIPE, WITNESSED E	3Y:	,		
SET NAIL & TAG #28414, SOUTH SID SET NAIL & TAG #28414, EAST SIDE SET NAIL & TAG #28414, NORTH SID FND. NAIL & TAG #25832, WEST SID	UTILITY POLE, N45°V DE 21" WALNUT, S81°	V, 65.48 FEET PW, 108.15 FEET	MINIMINIA OF MIC	Mining Strict Control of the Control

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1978

\* MAHIEU PROFESSIONAL & SURVEYOR NO. 28414 SELLING PROFESSIONAL NO. 28414 SELLING PROFESSIONA

MEVISED JAN, 1963 REVISED OCT, 1995

## M-2 Continued Page 2

3. LCRC in Liber 4, Page 265 dated July 29, 1978 by Richard W. Steadman, P.S. 11370. Found a railroad spike in the intersection of Vaughn and Kelly Roads, dug hole, and below railroad spike about 2 feet deep, found well rotted wood stake. Raised location of wood stake to surface with ½" iron pipe. Witnessed by:

10" HICKORY N.E. 45.61 FEET
TELEPHONE POLE, S.E. 53.98 FEET
28" WALNUT, S.S.E., 91.79 FEET
C/L 2" STEEL ROAD SIGN POST, S.W. 36.97 FEET

4. LCRC in Liber 5, Page 151 dated Jan 16, 1979 by Austin C. Williams, P.S. 21275. "Found 3/4" Iron rod in centerline of Kelly & Vaughi Roads. Measurements North & South in close accord with GLO records. Witnessed by:

NAIL & TAG 18" ASH N70"E 46.31'
NAIL & TAG 30" WALNUT S20"E 91.85'
CENTERLINE 2" STEEL SIGN POST S35"W 36.88"

5. AN ACT 132 SURVEY RECORDED IN LIBER 3, PAGE 706 BY AUSTIN C. WILLIAMS, P.S. 21275 CALLS FOR EAST 1/4 CORNER OF SECTION 1; NO MENTION OF CORNER MATERIAL. WITNESSES:

NAIL & TAG 18" ASH N70" E 46.31'
NAIL & TAG 30" WALNUT S20" E 91.85'
CENTERLINE 2" STEEL SIGN POST S35°W 36.88'

6. AN ACT 132 SURVEY RECORDED IN LIBER 6, PAGE 196 BY LARRY BRYAN, P.S. 25832 CALLS FOR EAST 1/4 CORNER AS A FOUND PIPE AND CAP CENTERLINE OF KELLY & VAUGHN ROADS, LIBER 4, PAGE 265. WITNESSED BY:

FOUND NAIL & TAG NORTH SIDE 20" WALNUT, S80°W 108.86' SET NAIL & TAG WEST SIDE 36" WALNUT, S25°E 91.79' SET NAIL & TAG SOUTH SIDE 18" HICKORY, N50°E, 45.61'

7. AN ACT 132 SURVEY RECORDED IN LIBER 7, PAGE 372 BY LARRY BRYAN, P.S. 25832 CALL FOR EAST 1/4 CORNER, SECTION 1, T1N, R1W, LIBER 5, PAGE 151. "FOUND 1/2" PIPE WITH CAP AT INTERSECTION OF VAUGHN & KELLY ROADS.

FOUND NAIL & TAG EAST SIDE 15" HICKORY, NE 45.67'
FOUND NAIL & TAG #25832, WEST SIDE 30" WALNUT, SSE, 91.79'
FOUND NAIL & TAG, NORTH SIDE 14" WALNUT, S70°W, 108.84'
CENTERLINE ROAD SIGN POST, N45°W, 38.09"

