

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>36</u>	T. <u>1</u> N. <u>1</u> R. <u>1</u> <del>E.</del> <u>W.</u>	<u>K-11, K-12, K-13</u>
2. PROPERTY CONTROLLING IN SECTION <u>36</u>	T. <u>1</u> N. <u>1</u> R. <u>1</u> <del>E.</del> <u>W.</u>	
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ <del>E.</del> <u>W.</u>	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, D. Scott do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on Sept. 25 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on Sept. 25 1973, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- K-11 Found 1/2" iron pipe @ Olds Road. Recovered with notes from Polaris Surveying Lansing, Mich.
- K-12 Found 1/2" iron rod 3" below gravel surface. Recovered with notes from Polaris Surveying Lansing, Mich.
- K-13 Found "T" shaped iron 2" below gravel @ Peacock Rd. Recovered with notes from Consumers Power Co. Jackson, Mi.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-11	NW Corner Section 36, T.1N, R.1W.	S 49° W 36.8'	Sign Post	N 10° E 25.02'	Telephone Post
		N 59° W 49.13'	10" Sharp Bark Hickory	S 46° E 35.52'	Telephone Post
K-12	W 1/4 Corner Section 36, T.1N, R.1W.	S 84° E 29.39'	20" White Oak	S 40° W 50.65'	26" Maple
		S 25° E 55.90'	20" White Oak	N 68° W 28.96'	27" Maple
K-13	SW Corner Sect on 36, T.1N, R.1W.	West 32.92'	6" Black Walnut	S 28° W 31.17'	15" Tully Oak
		N 26° W 49.22'	5" Black Walnut	S 86° E 17.4'	2" diameter iron pipe 220 feet 3" high

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 12029 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR DATE \_\_\_\_\_ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_