

INGHAM

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY <u>36</u>	T. <u>1</u> N. <u>1</u> R. <u>1</u> W.	<u>L-11, L-13</u>
2. PROPERTY CONTROLLING IN SECTION <u>36</u>	T. <u>1</u> N. <u>1</u> R. <u>1</u> W.	<u>L-11, L-13</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ R. _____ E. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, D. Scott do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram-over) were, in a field survey on Oct. 18 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on Oct. 18 1973, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

L-13 Set $\frac{1}{2}$ mi. post
 White Oak 7" N68°E 40 Links
 Dogwood 9" N73°W 32 Links

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

L-11 Found R.R. spike in Road intersection. Recovered with notes from Polaris Surveying Lansing, Mich.

L-13 Found $\frac{3}{4}$ " pinched iron pipe 2" below surface and 1" West of E. Road. Recovered with notes from Polaris Engineering Inc. Lansing, Mich.

This Corner Recorded by Polaris Engineering Inc.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-11 N $\frac{1}{4}$ Corner Section 36, T.1N, R.1W
 S37°E 57.87' Telephone Pole N17°W 43.1' "Yield" Sign Post
 S46°W 41.8' Street Sign Post N58°E 55.19' 10" Street Sign Post

L-13 S $\frac{1}{4}$ Corner Section 36, T.1N, R.1W
 S52°W 20.58' 20" Oak
 N85°W 17.41' 18" Hickory
 S75°E 25.73' 24" Oak

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12029 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____