LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY 24	T. 1 , R. 1 w.	M-7	
2. PROPERTY CONTROLL- ING IN SECTION——	,T N. E. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. E. W.		
4. LOT NO , RECO	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
I, Donald L. Bissell, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November, 19_75_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
M-7			
Found stone with br	ick around it.		
			(
C. Description of monument for c	omer and accessories establish	ned to perpetuate locating the	position of the corner:
M-7 3/4" pipe with pl N 15° E, 7.76', 7" W S 2° E, 30.28', 28" W N 39° E, 60.22', Power	astic can #12029 (D.		•
SIGNED BY			
SURVEYOR'S MICHIGAN REGIS			(SEAL)
FOR STATE AND UNITED STA	TES AGENCIES:		M
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	5-25-78
APPROVED AND SIGNED BY_	MICHIGAN REGISTERED LAND	SURVEYOR DATE_	(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. 18655

PAGE

5